

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2008 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including Boat Survey Erosion**

**Sacramento River Basin**

<b>RD0536</b>	Overall LMA Rating	Total LMA Miles				
<b>Reclamation District No. 0536</b>	<b>U</b>	<b>10.70</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	11.54	4.41	29.18	272.71%		
Trim / Thin Trees	0.08		0.08	0.75%		
Encroachments					0.46	
Erosion / Bank Caving	0.01		0.01	0.09%		
Crown Surface / Depressions / Rutting	4.78	0.67	7.46	69.72%		
<i>LMA Totals:</i>	16.41	5.08	36.73	343.27%	0.46	0.00

  

<b>Unit No. 01 Lindsey Slough</b>	Overall Unit Rating	Total Unit Miles				
	<b>U</b>	<b>5.70</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	2.30	2.61	12.74	223.51%		
Trim / Thin Trees	0.08		0.08	1.40%		
Encroachments					0.46	
Crown Surface / Depressions / Rutting		0.67	2.68	47.02%		
<i>Unit Totals:</i>	2.38	3.28	15.50	271.93%	0.46	0.00

  

<b>Unit No. 02 Yolo Bypass</b>	Overall Unit Rating	Total Unit Miles				
	<b>U</b>	<b>5.00</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	9.24	1.80	16.44	328.80%		
Erosion / Bank Caving	0.01		0.01	0.20%		
Crown Surface / Depressions / Rutting	4.78		4.78	95.60%		
<i>Unit Totals:</i>	14.03	1.80	21.23	424.60%	0.00	0.00

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2008 Levee Inspection Results**

**Reclamation District No. 0536**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			U	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 0536**

Waterway			Bank	Unit Miles
Unit No. 01 Lindsey Slough			Right	5.70
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/16/2008		10/9/2008	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 0536**

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Lindsey Slough						Right	5.70	10/09/2008		Herman Phillips	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.59	2.95	Earthen Levee	Vegetation	CR	U	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: This section was corrected from 1.76 thru to 2.95.	38.248757 ° -121.760635 °	38.255895 ° -121.733525 °		2
2	0.61	1.09	Earthen Levee	Vegetation	CR	M	Remove the wild growth other than native grasses from the levee slopes.	38.248938 ° -121.760347 °	38.255485 ° -121.757567 °		16
3	1.09	1.76	Earthen Levee	Crown Surface / Depressions / Rutting	WS	U	Regrade the crown roadway for proper drainage. Inspector Comments: This levee section has no gravel. This should be an all weather road with a graded graveled crown roadway which can be driven even in wet conditions.	38.255483 ° -121.757567 °	38.259617 ° -121.749978 °		17
4	1.52	1.54	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.258750 ° -121.753975 °	38.258673 ° -121.753615 °		4
5	1.52	1.57	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.258672 ° -121.753952 °	38.258717 ° -121.752898 °		18
6	1.87	2.01	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.259708 ° -121.748327 °	38.257982 ° -121.747388 °		19
7	3.79	4.86	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.251005 ° -121.725423 °	38.245508 ° -121.709817 °		20
8	4.19	4.26	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.249522 ° -121.718727 °	38.248725 ° -121.717858 °		21
9	4.52	4.58	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.249272 ° -121.713403 °	38.248735 ° -121.712503 °		22
10	4.54	4.56	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.249198 ° -121.713083 °	38.248968 ° -121.712773 °		12
11	4.61	4.65	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.248395 ° -121.712172 °	38.248018 ° -121.711890 °		23
12	4.62	4.64	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.248317 ° -121.712075 °	38.248118 ° -121.711935 °		13
13	4.65	4.80	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.248018 ° -121.711887 °	38.246072 ° -121.710687 °		24
14	4.86	4.94	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.245508 ° -121.709817 °	38.245600 ° -121.708292 °		25
15	4.90	4.94	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.245427 ° -121.708922 °	38.245597 ° -121.708290 °		26
16	5.17	5.56	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.245200 ° -121.704740 °	38.245583 ° -121.697632 °		27
17	5.17	5.63	Earthen Levee	Encroachments	WS	PO	Fences	38.245230 ° -121.704743 °	38.244785 ° -121.697200 °		28

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2008 Levee Inspection Results**

**Reclamation District No. 0536**

Waterway			Bank	Unit Miles
Unit No. 02 Yolo Bypass			Right	5.00
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/16/2008		10/10/2008	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 0536**

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 02 Yolo Bypass						Right	5.00	10/10/2008		Herman Phillips	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.02	2.11	Earthen Levee	Vegetation	CR	M	Remove the wild growth other than native grasses from the levee slopes.	38.243998 ° -121.696947 °	38.214303 ° -121.693840 °		12
2	0.04	2.09	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.243813 ° -121.696933 °	38.214528 ° -121.693788 °		1
3	0.05	2.58	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.243623 ° -121.696702 °	38.207985 ° -121.690552 °		13
4	0.76	2.58	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.233377 ° -121.697990 °	38.207983 ° -121.690552 °		14
5	2.58	3.48	Earthen Levee	Vegetation	LS	U	Control annual grass and weeds on the levee slopes and easements.	38.207980 ° -121.690555 °	38.197137 ° -121.684470 °		15
6	2.58	3.48	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.207983 ° -121.690552 °	38.197137 ° -121.684472 °		16
7	2.59	3.48	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.207860 ° -121.690345 °	38.196983 ° -121.684448 °		8
8	2.59	4.41	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.207808 ° -121.690438 °	38.197070 ° -121.700870 °		17
9	3.47	4.41	Earthen Levee	Vegetation	CR	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: There has not been any maintenance on this levee section since my last inspection.	38.197137 ° -121.684375 °	38.197070 ° -121.700875 °		18
10	3.48	4.41	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.197137 ° -121.684472 °	38.197070 ° -121.700872 °		19
11	3.48	4.41	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.197137 ° -121.684475 °	38.197070 ° -121.700872 °		20
12	3.69	3.70	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection.	38.196982 ° -121.688350 °	38.196850 ° -121.688542 °		10
13	3.69	3.71	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.196927 ° -121.688323 °	38.196838 ° -121.688765 °		11

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected